



Beckett Bridge *PD&E Study*



Recommended Alternative Closer to Yacht Club Docks

- South Edge of Bridge 8 feet closer to docks
- Measures to Mitigate Potential Access Issues
- Consider Eliminating Fender on South Side
- Install Plastic Timber Bumpers on Piles or Piers to Prevent Boat Damage

Edge of
New Bridge

