




Beckett Bridge *PD&E Study*

Historic Whitcomb Bayou Circa 1921

Rehabilitation Alternative (No Widening)



- Rehabilitate or Replace Control House
- Install cathodic (corrosion) protection jackets on steel bascule pier helper piles (crutch bents)
- Replace the bascule leaf (movable span)
- Repair deteriorated concrete of the bascule pier and rest pier, and provide cathodic (corrosion) protection

Note: The bascule leaf and bascule pier are the only remaining elements of the original 1924 Bridge